## **Inventory Summary**

PWS Name: Town North Village

PWSID: TX1520094

**Purpose of this worksheet:** For water systems to provide a summary of the service line inventory, including information on ownership, inventory format, and the number of service lines for each of the four required materials classifications.

**Note:** Cells that have a superscript \* are required fields.

Part 1. General Information		
1. Is this the <b>Initial Inventory</b> or an <b>Inventory Update</b> ? Initial Inventory		
2a. Who <b>owns the service lines</b> in your system? <i>If other, please explain below.</i> <sup>x</sup>	Ownership is split	
2b. Is there documentation that defines service line ownership in your system, such as a local ordinance? If yes, please describe below and explain where ownership is split (e.g., property line, curb stop).	Yes	
3a. Describe when lead service lines were generally installed in your system below.		
N/A		
3b. When were lead service lines banned for the system? Reference the state or local ordinance that banned the use of lead in your system.		
1986 Safe Drinking Water Act		
4. Are there lead goosenecks, pigtails or connectors in the system?	No	

## Part 2. Inventory Summary Table <sup>1</sup>

When using the **Detailed Inventory** worksheet, the classifications in the Column "Entire Service Line Material Classification" (Column Q) will be used to calculate the total number of service lines for each of the four material classifications below. **Remember this is the classification for the entire service line.** 

Service Line Material Classification	Definition	Total Number of Service Lines (REQUIRED to be reported under the LCRR) <sup>x</sup>
Lead	Any portion of the service line is known to be made of lead. <sup>2</sup>	0
Galvanized Requiring Replacement (GRR)	The service line is not made of lead, but a portion is galvanized and the system is unable to demonstrate that the galvanized line was never downstream of a lead service line.	0
Non-Lead	All portions of the service line are known NOT to be lead or GRR through an evidence-based record, method, or technique.	120
	The service line material is not known to be lead or GRR. For the entire service line or a portion of it (in cases of split ownership), there is not enough evidence to support material classification.	0
TOTAL		120

## Notes

<sup>1</sup>This summary table is for reporting material for the entire service line connecting the water main to the customer's plumbing. See the **Classifying SLs** worksheet for additional guidance on assigning a materials classification to the entire service line when ownership is split. Remember that systems must track the system-owned and customer-owned portions separately in their inventory.

TCEQ-20943 (Rev. 12/16/2022) Page 1

<sup>&</sup>lt;sup>2</sup> A lead-lined galvanized service line is consistent with the definition of an LSL under the LCRR ("a portion of pipe that is made of lead, which connects the water main to the building inlet") (40 CFR §141.2) and must therefore be classified in the inventory as an LSL. Do not, however, count non-lead service lines with a lead gooseneck or pigtail as lead service lines.